



















Questions? Comments? 303-255-7770


Updated: 12/26/19



Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Wes Brown Water Treatment Plant 3651 E 86th Ave	Downstairs Conference Room	350	ND	✓	1/23/18	0643
	Breakroom Upstairs	300	ND	✓	1/23/18	0648
	Downstairs Cubicals	350	ND	✓	1/23/18	0652
	Ops Room	ND	ND	✓	1/23/18	0658
	Fountain Up	210	ND	✓	1/23/18	0659
	1st Lab Faucet	13	0.78	✓	1/23/18	0732



Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Thornton Water Treatment Plant 9520 Ellen Ct.	Lab Sink	ND	ND	✓	2/15/18	0010
	Kitchen	10	ND	✓	2/15/18	0010
	Drinking Fountain	260	0.9	✓	2/15/18	0010




Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Thornton Arts and Cultural Center 9209 Dorothy Blvd.	Breakroom	140	1.2	✓	1/24/18	0715
	Fridge Dispenser	3.3	ND	✓	1/24/18	0716
	Fountain, Bottom	200	0.78	✓	2/1/18	0800
	Fountain, Top	160	0.85	✓	2/1/18	0800

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Active Adult Center 9471 Dorothy Blvd	Sink 1	130	0.6		1/23/18	0607
	Sink 2	120	0.74		1/23/18	0608
	Sink 3	180	2.9		1/23/18	0609
	Sink 3 - 2nd Test	140	1.8		2/20/18	0618
	Sink 3 - After 60sec flushing	110	0.62		2/20/18	0621
	Sink 4	110	2.1		1/23/18	0610
	Sink 4 - 2nd Test	120	2.3		2/20/18	0618
	Sink 4 - After 60sec flushing	110	0.57		2/20/18	0621
	Stovetop	54	1.4		1/23/18	0612
	Coffee 1	77	0.77		1/23/18	0615
	Coffee 2	69	ND		1/23/18	0618
	Coffee 3	67	ND		1/23/18	0620
	Fountain 1 Bottle Filling	160	ND		1/24/18	0612
	Fountain 1 Faucet	140	ND		1/24/18	0613
	Fountain 2 Fitness Center	130	ND		1/24/18	0615
	Iced Tea Maker	54	ND		1/24/18	0608
	Downstairs Fountain	360	1.4		1/14/19	0745
	Downstairs Pottery Room Sink	230	ND		11/20/19	0700

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Park Village Pool 4051 Summit Grove Pkwy.	Fountain	860	ND		8/18/18	0852

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
City Pool 2141 E. 95th Ave.	Shower Fountain	280	ND		8/10/18	0820
	Lockers Fountain	120	ND		8/10/18	0819

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Fire Station 1 9451 Dorothy Blvd.	Fridge Dispenser	11	ND		1/19/18	0550
	Kitchen Sink	49	ND		1/19/18	0548
	Coffee Maker	28	ND		1/19/18	0552

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Fire Station 2 9667 Huron St.	Coffee Maker	60	0.85		2/6/18	1444
	Kitchen Faucet	20	ND		2/6/18	1441
	Fridge Dispenser	76	ND		1/11/19	1135

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Fire Station 3 11257 Birch Dr.	Kitchen Sink	32	ND	✓	2/6/18	0001
	Coffee Maker	31	ND	✓	2/6/18	0009







Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Fire Station 4 1400 E. 128th Ave.	Kitchen Faucet	60	ND	✓	2/6/18	1350
	Coffee Maker	38	ND	✓	2/6/18	1352
	Rev. Osmosis Faucet	ND	ND	✓	2/6/18	1356
	Stove Cookpot	120	ND	✓	2/6/18	1400
	Fridge Dispenser	100	ND	✓	1/11/19	1240



Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Fire Station 5 14051 Colorado Blvd.	Kitchen Faucet	80	ND	✓	2/6/18	0038
	Rev. Osmosis	3.4	ND	✓	2/6/18	0038
	Kitchen Coffee Maker	76	0.67	✓	2/6/18	0046
	Fridge Dispenser	160	ND	✓	2/6/18	0048
	Community Room Sink	32	ND	✓	2/6/18	0048
	Community Room Office	56	1.4	✓	2/6/18	0050



Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
	Breakroom	190	ND	✓	1/24/18	0620









Community Center 2211 Eppinger Blvd.	Main Drinking Fountain	220	ND		1/24/18	0624
	Downstairs Drinking Fountain	130	ND		1/24/18	0627
	PreSchool	170	1.1		1/24/18	0630
	PreSchool - 2nd Test	170	1.1		2/21/18	0715
	PreSchool - After 60sec flushing	170	1.0		2/21/18	0718
	Billiards	170	0.93		1/24/18	0634

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Margaret Carpenter Rec Center 11151 Colorado Blvd.	Womens Locker Sink	140	ND		3/13/18	0506
	Mens Locker Sink	130	ND		3/13/18	0507
	Pool, Left Fountain	210	ND		3/13/18	0509
	Pool, Right Fountain	180	ND		3/13/18	0510
	Weight Room Fountain	120	ND		3/13/18	0512
	Racquet Hall, Left Fountain	64	ND		3/13/18	0513
	Racquet Hall, Right Fountain	77	ND		3/13/18	0514
	Treadmills Fountain	180	ND		3/13/18	0517
	Basketball Gym Fountain	110	ND		3/13/18	0520
	Front Desk, Right Fountain	110	ND		3/13/18	0522
	Front Desk, Left Fountain	130	ND		3/13/18	0523
	Running Track Fountain	190	ND		3/13/18	0528
	Fitness/Dance Fountain	160	ND		3/13/18	0530
	Staff Lounge Sink	80	ND		3/13/18	0533
	Gymnastics, Lower Fountain	130	ND		3/13/18	0536
	Gymnastics, Upper Fountain	160	ND		3/13/18	0537
Main Kitchen, Left Sink	110	ND		3/13/18	0540	

	Main Kitchen, Right Sink	170	ND		3/13/18	0543
	Main Kitchen, Small Hand Sink	150	ND		3/13/18	0545
	Main Kitchen, Coffee Maker	6	ND		3/13/18	0547
	Preschool, Pink Sink	140	0.63		3/13/18	0552
	Preschool, Small Sink	220	ND		3/13/18	0553
	Childcare, Green Sink	200	0.7		3/13/18	0558
	Childcare, Small Sink	130	ND		3/13/18	0600

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Margaret Carpenter Park 3498 E. 112th Ave.	Right Fountain	380	4.9		8/18/18	0657
	Left Fountain	380	5.1		8/18/18	0658

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Margaret Carpenter Park Boathouse 3498 E. 112th Ave.	Left Fountain	700	1.1		8/18/18	0705
	Right Fountain	390	1.8		8/18/18	0706

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Thorncreek Golf Course 13555 Washington St.	Maintenance bldg Sink	52	ND		6/13/18	0615
	Maintenance bldg Fountain	430	ND		6/13/18	0620
	Maintenance bldg Coffee Maker	3.1	4.8		7/3/18	0615
	Clubhouse Kitchen Sink 1	290	ND		6/13/18	0730
	Clubhouse Kitchen Sink 2	700	1.1		6/13/18	0730
	Clubhouse Kitchen Sink 3	540	ND		6/13/18	0730
	Clubhouse Coffee Maker Right	12	34		6/13/18	0728
	Clubhouse Coffee Maker Right - 2nd Test	6	1.2		7/3/18	0730

Clubhouse Coffee Maker Left	5.3	2.7	✓	6/13/18	0730
Clubhouse Ice/Water Machine	68	ND	✓	6/13/18	0734
Clubhouse Tea Brewer	180	ND	✓	6/13/18	0734

**Clubhouse re-sampled and verified to be under EPA action level of 15 ug/L.*















Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Trailwinds Park 13385 Holly St.	Skate Park Lower Fountain	440	15	✗	8/15/18	0744
	Skate Park Lower Fountain - 2nd Test	1500	48	✗	10/10/18	0752
	Skate Park Upper Fountain	500	12	✓	8/15/18	0745
	Skate Park Upper Fountain - 2nd Test	1300	40	✗	10/10/18	0750
	Pavilion Lower Fountain	1700	1.5	✗	8/15/18	0720
	Pavilion Lower Fountain - 2nd Test	2300	1.6	✗	10/10/18	0755
	Pavilion Upper Fountain	1800	1.4	✗	8/15/18	0722
	Pavilion Upper Fountain - 2nd Test	2300	1.8	✗	10/10/18	0754

**Above EPA action level of 15 ug/L for Lead, 1300 ug/L for Copper.*

**Trailwinds fountains taken out of service for winter, remediation will be addressed before opening.*















Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Municipal Service Center/Parks 8651 Colorado Blvd.	1st Floor Kitchen	460	0.87	✓	4/24/18	0609
	1st Floor Fountain	540	0.9	✓	4/24/18	0611
	Upstairs Kitchen Sink	270	1.2	✓	4/24/18	0615
	Upstairs Coffee Maker	9.4	ND	✓	4/24/18	0616
	Office Kitchen Sink	620	2.0	✓	4/24/18	0620
	Mowshop Fountain	760	0.65	✓	4/24/18	0625

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
<p style="text-align: center;">Fire Station 6 (AKA: Public Safety Facility) 13150 Quebec St.</p>	FD1, Kitchen Sink	450	ND	✓	2/11/19	1030
	FD2, Kitchen Coffee Maker	100	ND	✓	2/11/19	1032
	FD3, Kitchen Fridge	ND	ND	✓	2/11/19	1035
	FD4, Water Bottle Station	2.4	ND	✓	2/11/19	1037
	FD5, Ice Maker	3.1	ND	✓	2/11/19	1040
	FD6, Training Room Sink	420	0.50	✓	2/11/19	1043
	FD7, Training Room Coffee Maker	ND	0.56	✓	2/11/19	1045
	FD8, Fitness Room Bottle Station	180	ND	✓	2/11/19	1048
	PD1, Detective Coffee Maker	5.9	ND	✓	2/11/19	1105
	PD2, Detective Fridge	4.2	ND	✓	2/11/19	1107
	PD3, Break Room Coffee Maker	3.6	ND	✓	2/11/19	1114
	PD4, Break Room Fridge	6.9	ND	✓	2/11/19	1116
	PD5, Detective Sink	600	ND	✓	2/11/19	1120
	PD5, Break Room Sink	380	ND	✓	2/11/19	1123

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Infrastructure Maintenance Center 12450 Washington St.	Downstairs Coffee	170	2.1		5/16/18	0512
	Downstairs Kitchen Sink	150	ND		5/16/18	0514
	Downstairs Fountain, Left	180	ND		5/16/18	0515
	Downstairs Fountain, Right Top	190	ND		5/16/18	0517
	Downstairs Fountain, Right Bottom	180	ND		5/16/18	0518
	Streets Corner Office Sink	260	ND		5/16/18	0534
	Streets Fountain in Bay, Top	180	ND		5/16/18	0537
	Streets Fountain in Bay, Bottom	160	ND		5/16/18	0538
	North Upstairs Lounge Kitchen Sink	140	ND		5/16/18	0539
	North Upstairs Lounge Coffee Maker	190	ND		5/16/18	0540
	Outside Room #210 Fountain, Right Bottom	170	ND		5/16/18	0547
	Outside Room #210 Fountain, Right Top	190	ND		5/16/18	0548
	Outside Room #210 Fountain, Left	150	ND		5/16/18	0549
	Fleet, Entrance Sink, Left	200	1.3		5/16/18	0559

	Fleet, Entrance Sink, Right	270	ND		5/16/18	0600
--	-----------------------------	-----	----	---	---------	------

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Lambertson Historic Farm House North Washington Street & 100th Ave.	Well water	3.4	ND		3/11/19	1340

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Civic Center/City Hall 9500 Civic Center Dr.	1st Floor Staff Lounge Fountain	310	2.4		5/30/18	0545
	1st Floor Staff Lounge Sink	68	ND		5/30/18	0547
	Room 1044 Coffee Maker	70	2.0		5/30/18	0552
	Front Lobby Left Fountain	310	1.9		5/30/18	0558
	Front Lobby Right Fountain	260	1.8		5/30/18	0559
	2nd Floor Hall Left Fountain	570	1.2		5/30/18	0601
	2nd Floor Hall Right Fountain	520	1.1		5/30/18	0602
	HR Kitchen Sink	270	ND		5/30/18	0604
	HR Coffee Maker	270	2.0		5/30/18	0606
	3rd Floor Hall Left Fountain	680	ND		5/30/18	0612
	3rd Floor Hall Right Fountain	660	ND		5/30/18	0614
	Lower Level Fountain Outside Elevator	410	1.5		5/30/18	0617
	IT Dept Kitchen Fridge Dispenser	83	ND		5/30/18	0621
	Lower Level Kitchen #1008	490	1.2		5/30/18	0622

Council Conference Coffee Maker	340	7.1		5/30/18	0628
Council Conference Sink	500	5.7		5/30/18	0629
Room #180 Sink	200	ND		5/30/18	0634
Kitchen Outside #110	350	1.2		5/30/18	0636
Kitchen Sink Near #138	150	ND		5/30/18	0641
Lounge Near #138 Coffee Maker	78	ND		5/30/18	0642
City Development Front Lobby Left Fountain	200	ND		5/30/18	0652
LL08 Kitchen Sink	220	ND		5/30/18	0654
LL08 Coffee Maker	220	3.2		5/30/18	0655
Outside LL00 Left Fountain	200	ND		5/30/18	0700

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Civic Center/City Hall 9500 Civic Center Dr.	Outside LL00 Right Fountain	180	ND		5/30/18	0702
	Fire Admin Kitchen Sink	400	ND		5/30/18	0748
	Fire Admin Coffee Maker	60	ND		5/30/18	0750
	Fire Admin Fridge Dispenser	240	ND		5/30/18	0758
	City Manager Office Sink	440	1.3		5/30/18	0804
	City Manager Fridge Dispenser	460	ND		5/30/18	0805
	Reprographics Sink	310	1.0		5/30/18	0809
	LL39 Fountain Locker Rooms	120	ND		5/30/18	0814
	Outside building inspection	330	ND		5/30/18	0820

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
	Main lobby, Left Fountain	360	ND		6/4/18	0616
	Main lobby, Right Fountain	350	ND		6/4/18	0618
	Room #4053 Fridge Dispenser	150	ND		6/4/18	0620



Justice Center - Police
9551 Civic Center Dr.

Room #4053 Kitchen Sink	360	ND	✓	6/4/18	0621
Room #4053 Coffee Maker	10	ND	✓	6/4/18	0624
Detectives Fridge Dispenser	6.3	ND	✓	6/4/18	0625
Detectives Coffee	54	ND	✓	6/4/18	0628
Detectives Kitchen Sink	310	ND	✓	6/4/18	0629
Room #3038 Fridge Dispenser	6.2	ND	✓	6/4/18	0630
Room #3038 Coffee Maker	23	ND	✓	6/4/18	0631
Room #3038 Kitchen Sink	150	ND	✓	6/4/18	0632
Room #3013 Kitchen Sink	280	ND	✓	6/4/18	0634
Room #1018 Coffee Maker	170	1.4	✓	6/4/18	0636

Justice Center - Police
9551 Civic Center Dr.

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Justice Center - Police 9551 Civic Center Dr.	Room #1018 Kitchen Sink	200	ND	✓	6/4/18	0637
	Room #1018 Fridge Dispenser	56	ND	✓	6/4/18	0639
	Room #3063 Kitchen Sink	320	ND	✓	6/4/18	0642
	Room #3063 Coffee Maker	180	ND	✓	6/4/18	0643
	Room #1066, Right Fountain	500	ND	✓	6/4/18	0646
	Room #1066, Left Fountain	490	5.3	✓	6/4/18	0647
	Room #2045 Fridge Dispenser	5.2	ND	✓	6/4/18	0648
	Room #2045 Kitchen Sink	240	ND	✓	6/4/18	0649
	Room #C324 Fridge Dispenser	9	ND	✓	6/4/18	0653
	Room #C324 Kitchen Sink	320	ND	✓	6/4/18	0654
	Room #3024 Kitchen Sink	300	ND	✓	6/4/18	0700
	Room #3024 Fridge Dispenser	84	ND	✓	6/4/18	0701
	Exercise Room, Right Fountain	350	ND	✓	6/4/18	0702

	Exercise Room, Left Fountain	330	ND		6/4/18	0704
--	------------------------------	-----	----	---	--------	------

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Northern Lights Ball Fields 13800 York St.	Lower Fountain	870	ND		8/15/18	0737
	Upper Fountain	860	ND		8/15/18	0738

Building	Location	COPPER (ug/L)	LEAD (ug/L)	CONSIDERED SAFE FOR CONSUMPTION	Sample Date	Sample Time
Thornton Sports Complex 10370 McKay Rd.	South Fountain	1100	ND		8/9/18	0703